Work Ord Monday, June 0													Page 1
Item ID: Revision ID: Item Name:	D4017-9 Rib			Accept						Setup	Start Stop		
Start Date: Required Date: Reference:	6/7/2010 6/21/2010	Start Qty: 6.00 Req'd Qty: 6.00				Cust Item Customer							
Approvals:	Process Pla	n:	Date/ <i>()-()-()</i> Date:	Toolin SPC (Y			Date:			Run	Start Stop		
Sequence ID/ Work Center II)	Operation Description		Set Run	Up/ Hours	Tool ID	Tool #	Plan Code	Accep Qty	t Re Qt		Reject Number	Insp. Stamp
Draw Nbr D4017	Revi	ision Nbr											
100 Large Fab Large Fab			e as per dwg D4017 and remove identify marks	0.00	SAP 10-0	P6-09		(B				
QC Quality Control		QC5- Inspect part com	pleteness to step on W/O	0.00	5 3	show (10			(le			<u> </u>	

120 Packaging Identify as per dwg & Stock Location: WA

0.00

Packaging

Memo

0.00

Dart Aerospace Lt	d
--------------------------	---

W/O:			WO	RK ORDER CHANG	SES					
DATE	STEP	PR	OCEDURE CHA	IGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			7-11-							
						:				
Part No	:	PAR #:	Fault Categ	jory:	NCR:	Yes N	lo DQ	A:	Date:	
		olution:								
NCR:				R NON-CONFORM						
DATE	STEP	Description of NC			tion B		Verific	cation	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti		Chief Eng	QC Inspector
										i.
										-
									'	

Work Order ID 59538

Monday, June 07, 2010 10:41:09 AM



Page 2

Item ID:

D4017-9

6/7/2010

Accept



Setup Start

Stop



Revision ID:

Item Name: Rib

Required Date: 6/21/2010

Start Qty: 6.00

Req'd Qty: 6.00



Cust Item ID: Customer:

Tool ID

Reference:

Start Date:

_		-
Δn	prov	ale.
	ייטנקי	aıs.

Process Plan:

Date:

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/

Work Center ID

130

Description QC21- Final Inspection - Work Order Release

Operation

Set Up/ **Run Hours**

Tool # Plan

Code

Accept Qty

Reject Qty

Reject Insp. Number

Stamp

Memo

0.00

0.00

Quality Control

10/06/10 9kg 10-6-10 (4)

Dart A	erospa	ace Ltd
--------	--------	---------

W/O:			W	ORK ORDER CHA	ANGES					* .
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						:				
,										
								,		
Part No	:	PAR #:	Fault Cate	egory:	NCF	: Yes	No DQ	٨:	Date:	
		esolution:	Disposition	on:	QA:	N/C CId	osed:			
NCR:		\	WORK ORD	ER NON-CONFO	RMANCE	(NCR)			,
DATE	STEP	Description of NC		Corrective Action	Section B	0: 0	Verific	ation	Approval	Approval
		Section A	Initial Chief Eng	Action Descript Chief Eng	lion	Sign & Date	Section	on C	Chief Eng	QC Inspector
								:		
						-				

Picklist Print

Monday, June 07, 2010 10:41:13 AM

Work Order ID: 59538

Parent Item:

D4017-9

Parent Item Name:

Comments:

IPP RevA: new issue DD 09.11.26 verified by:EC

per dwg RevA DD 10.03.06 verified by:EC

DD 10.04.16 verified by:EC

IPP Rev:B as

IPP Rev:C as per dwg RevB

Start Date: 6/7/2010

Required Date: 6/21/2010

Start Qty: 6.00

Required Qty: 6.00

Component	Item	ID/
1 400 ATTOO 500		^

Replacement Mfg/ M304TS0.500W.049

Rib

Purchased

Bin Primary No

Last

Route 100

Unit of f

Qty on 189.4263

Qty per Kit Total 2.28166

14.41048

Qty

Status

Page 1

Date




oquaic ruoing	Square	Tut	oing
---------------	--------	-----	------

SAD	10-06	-BC

Location	Loc Qty	Loc Code	
MAT	182.3299458		
114004	0		
114426	9.2647		
114807	173.065246		14.41048
MAT018	4.4738		
114004	0.5		
114161	3.9738		
WA	2.62251		
114724	2.62251		411


	Dart	Aeros	pace	Ltd
--	------	--------------	------	-----

W/O:			GES							
DATE	STEP	PRO	CEDURE CH	ANGE	Ву			Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									<u> </u>	
Part No	:	PAR #:	Fault Cate	egory:	NCR: Y	es N	o DQ	\ :	Date:	
				Disposition: Q						
NCR:		V	VORK ORD	ER NON-CONFORM	ANCE (N	CR)		······		
DATE STEP		Description of NC	Description of NC Corrective Ac		tion B		Verification		Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng		gn & ate	Section	on C	Chief Eng	QC Inspector
								:		
			1			i				•




Dart Aerospace Ltd	Dart A	leros	pace	Ltd
---------------------------	--------	-------	------	-----

	 	······································	· · · · · · · · · · · · · · · · · · ·									
W/O:		WORK ORDER CHANGES										
DATE STEP		PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
1												
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date:				
		olution:	Dispositio	າ:	QA: N/C C	osed:						
NCR:			WORK ORDI	ER NON-CONFORM	ANCE (NCF	R)						
DATE	STEP	Description of NC	Initial	tion B Sign 8	Verific		Approval	Approval				
·		Section A	Chief Eng	Action Description Chief Eng	Date	Secti	on C	Chief Eng	QC Inspector			
						_						



Dart	Aeros	pace	Ltd
------	-------	------	-----


W/O:			WC	RK ORDER CHANG	GES			
DATE	STEP	PROCEDURE CHANGE				Date C	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA: _	Date: _	
	Res	olution:	Disposition	1:	QA: N/C CI	osed:	Date: _	
NCR:		•	WORK ORDE	R NON-CONFORM	ANCE (NCR	2)	***************************************	
DATE	STEP	Description of NC	Corrective Action Section B Initial Action Description			Verification	on Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng	Sign & Date	Section C		QC Inspector
		-						



Dart Aerospa	ce	Ltd
--------------	----	-----

W/O:			W	ORK ORDER CHANG	iES		4		
DATE STEP		PR	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	egory:	NCR: Yes	No DQ	 A :	Date:	
		solution:							
NCR:				ER NON-CONFORM					
DATE	STEP	Description of NC	Corrective Action Section B			Verifi	ication	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date		ion C	Chief Eng	QC Inspector
								:	
<u> </u>									

Wo 59538



Dart Aerospace	Ltd
----------------	-----

W/O:			WC	ORK ORDER CHANG	iES				
DATE	STEP	PR	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		·					-	·	
						,			
Part No: PAR #:			Fault Cate	gory:	_ NCR: Yes	No DQA	ı:	Date:	
	Re	esolution:	Disposition	n:	_ QA: N/C CI	osed:		Date:	
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (NCF	R)			-
DATE STEP		Description of NC Corrective Action			ion B	Verific	ation	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section		Chief Eng	QC Inspector
			, .						
,									
							į		

2 W059538 8.0 2 PL Ø0.13 2 PL 2 PL D D 0.38 55.25 REF **D4017-1 RIB** 56.75 55.25 REF С **D4017-3 RIB** 55.25 **D4017-5 HINGE RIB** REF 0.049 **D4017-9 RIB** D4017-7 RIB NOTES: 1) MATERIAL -1 THRU -7: AISI 304/316 STAINLESS STEEL SQUARE TUBE, 0.75 X 0.75 X 0.049 WALL REF DART SPEC. M304TS0.750W.049 DESIGN -9: AISI 304/316 STAINLESS STEEL SQUARE TUBE, 0.50 X 0.50 X 0.049 WALL REF DART SPEC. M304TS0.500W.049 DART AEROSPACE LTD DRAWN HAWKESBURY, ONTARIO, CANADA 2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX CHECKED DRAWING NO. REV. B D4017 MFG. APPR. SHEET 5 OF 5 TITLE APPROVED SCALE 6) IDENTIFICATION: N/A
7) WEIGHT: SEE ASSEMBLED WEIGHTS SHORT BASKET BASE ASSY (350) NTS DE APPR. DATE COPYRIGHT © 2010 BY DART AEROSPACE LTD 10.03.25

Dart	Aer	osp	ace	Ltd
------	-----	-----	-----	-----

		•								
W/O:			WC	RK ORDER CHANG	ES					
DATE	STEP	PR	OCEDURE CHAI	CEDURE CHANGE By			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				-1			· · · · · · · · · · · · · · · · · · ·			
Part No	:	PAR #:	Fault Categ	Jory:	_ NCR:	Yes N	o DQ /	A:	Date:	
Resolution:										
NCR:			WORK ORDE	R NON-CONFORMA	ANCE	(NCR)			***************************************	W
DATE	STEP	Description of NC	Corrective Action Section Sectio			Sign & Ve			Approval	Approval
		Section A	Chief Eng	Chief Eng		Date	Section	on C	Chief Eng	QC Inspector
				•						
k. 										
						•				